
Eurasian Conformity (EAC) Certification Process

For manufacturers exporting to Kazakhstan, Kyrgyzstan, and Armenia

Manufacturer's process to obtain EAC CU TR 032 (pressure equipment) certification



Top 5 most frequently used guidelines for industrial manufacturers:

Low Voltage CU TR 004

Machinery Safety
CU TR 010

Equipment for use in potentially explosive areas

CU TR 012

EMC (Electro-magnetic compatibility)

CU TR 020


Pressure Equipment CU TR 032



To find out how LRQA can help you, visit www.lrqa.com, email info-usa@lrqa.com or call +1 866 971 LRQA

Eurasian Conformity (EAC) Certification Process

For manufacturers exporting to Kazakhstan, Kyrgyzstan, and Armenia





To find out how LRQA can help you, visit www.lrqa.com, email info-usa@lrqa.com or call +1 866 971 LRQA